


Error while updating a SENA device using Windows 10

Please follow these steps to change the driver signature  
throughput on your Windows 10 PC


### **Step 1:**

Click the Start Menu and select **Settings**.




### **Step 2:**

Click **Update and Security**.




### Step 3:

Click on **Recovery**




## Step 4:

Click **Restart now** under **Advanced Startup**.




## Step 5:

Click **Troubleshoot**.




## Step: 6

Click **Advanced options**.




## Step 7:

Click **Startup Settings**.



**Step 8:**


Click on **Restart**.



**Step 9:**



On the Startup Settings screen press 7 or F7 to disable driver signature enforcement.



Your computer will restart and you will be able to install non-digitally signed drivers.

Start the Sena Bluetooth Device Manager, and try the device recognition again.